




OFFICE OF THE MARION COUNTY SURVEYOR  
SECTION RECORD CORNER  
SECTION 6 TOWNSHIP 14 RANGE 5  
DATE: 4-18-08  
PARTY CHIEF: Wilcoxon  
CREW: \_\_\_\_\_  
TYPE OF MARKER: Harrison found  
METHOD OF ESTABLISHMENT: County: 10-15-02

IN. S.P.C. E ZONE NAD '83  
NAME: 14050602  
N: 493826.9824(m)  
E: 69852.1480(m)

Thompson Rd 5000 S



Section corner not set in original survey dated 1820. There is no reference to the corner in Franklin Township Legal Survey Book. March 1957 called nail and brass washer over stone. Corner reference, no date, called PK nail. 3-20-75 called railroad spike. 9-25-79 called PK nail. Excavated 11-2-87 stone found 17" down with iron pin. Harrison set. Re-tied 7-22-98. Re-tied 10-15-02 by Wilcoxon, Re-tied 4-18-08 by Wilcoxon.

14050602

REF.	DISTANCE	DESCRIPTION
1.	17.84'	Mag nail w/bw S PwP no# 10"up
2.	65.66'	PK nail W PwP#20-710 12"up
3.	89.03'	Due E to brass plug in steel box Franklin Road Centerline
4.	71.75'	Mag nail w/bw S PwP#105-710 18"up
5.	98.73'	Road nail W PwP#1-710 24"up
6.	125.25'	NW corner of garage for address 8411
7.	104.01'	SE corner of house Address 4942